

Attachment CC Radiation Machines

| Facility | Radiation Machine Model | Radiation Machine Head Serial Number | Condition |
|---------------|-------------------------------|--------------------------------------|-----------|
| BSDA | | | |
| CDF | Gendex GX 770 | 770-1743893 DP | G |
| MDC | Gendex GX 770 | 771-1741423DP | G |
| MTC | Belmont PHOT-XII | EX1160318 | E |
| | Belmont PHOT-XII | EX1160317 | E |
| | Gendex GX 770 | 770-17-43896-DP | G |
| | Belmont X-Caliber Panorex | 10980 | G |
| MRDCC | Orthophos 3 Sirona Pan | 16346 | G |
| | Gendex GX 770 | 773-173987DP | G |
| WDC | Gendex GX 770 | 771-1825679DP | G |
| ESDA | | | |
| ECI-E | Gendex GX 770 | 771-1749019DP | G |
| | Gendex GX 770 | 771-1675413DP | G |
| | Belmont X-Caliber Panorex | 1555870 | G |
| ECI-W | Gendex GX 770 | 770-1019704FP | G |
| JSDA | | | |
| BCF | Gendex 770 | 102526 | G |
| JCI | Gendex GX Pan Panoramic X-ray | 21463 | G |
| | Gendex 770 | 770-1205189DP | G |
| | Belmont PHOT-XII | EH11G0320 | E |
| JRH | Gendex GX 770 | 102492 | G |
| | Belmont X-Caliber Pan | 1553892 | G |
| MCI-J | Gendex 770 | 102516 | G |
| MCI-W | Gendex Expert DC 65 | 2016370 | E |
| | Gendex Orthorilix 9000 | 1701401DP | G |
| PATX | Gendex 770 | 102307 | G |
| WSDA-C | | | |
| NBCI | Gendex 765 | 11733 | E |
| | Gendex Orthorilix 8500 | 3640 | G |
| WCI | Gendex GX Pan Panoramic X-ray | 225135623ZDP | F |
| | Gendex 770 | 28663 | F |
| | Gendex 770 | 35389 | F |
| WSDA-H | | | |
| MCI-H | Gendex 770 | 5-0121 | G |
| | Gendex GX Pan Panoramic X-ray | 2251069111 | G |
| MCTC | Gendex Orthorilix 8500 | 7009/1994783 | E |
| | Gendex DC 75 | 1998590 | E |
| RCI | Gendex 770 | 106204 | G |
| | Belmont 096 | A05070 | F |